



GARY R. HERBERT  
Governor  
GREGORY S. BELL  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

### Minerals Regulatory Program

March 07, 2013

Reviewed: 

<b>Mine Name:</b> Point of Mountain (South Hansen)	<b>Permit Number:</b> M/035/0026
<b>Operator Name:</b> Geneva Rock Products	<b>Inspection Date:</b> September 30, 2009
<b>Inspector(s):</b> L Heppler	<b>Time:</b> 7:00 AM
<b>Other Participants:</b> Operator Representative	<b>Mine Status:</b> Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Bond Renewal Date:** 09-01-2014 **Bond Amount:** \$938,346 **Permit fee** is up to date

**Purpose of Inspection:** Routine annual Inspection. This site was last inspected as a large mine 07/20/2006, by Paul Baker.

**Inspection Summary:** There is a current NOI on file with the Division. Overall the Operation is well maintained - no erosional problems were noted, fence was maintained, no deleterious material was noted and roads were in good condition, Topsoil stockpiles were not reviewed by the Inspector on September 30, 2009. Every effort should be made to salvage top soil from the site prior to mining.

Photos were taken to document site conditions.

**Conclusions and Recommendations:** Operator is due for a periodic plan review next year, which includes a bond escalation review. OGM to continue annual inspections and monitor the site when in the area.

**Inspector's Signature**

LAH:pb

cc: Brent Sumsion

O:\M035-SaltLake\M0350026-PointMtn\inspections\Insp-09302009.doc






Overview of mine site – looking west



Overview of mine site – looking west



Overview of mine site – looking southwest



Overview of mine site – looking southwest





Fence on east perimeter



Upper slope of rock pit



Upper slope of rock pit



Lower slope of rock pit